



Honey Bee Manufacturing Ltd.
P.O. Box 120
Frontier, Sask. S0N 0W0
Phone (306) 296-2297
Fax (306) 296-2165
email: rick.norheim@honeybee.ca

SERVICE BULLETIN

MANDATORY



FIX ON FAILURE

INFORMATION ONLY

Ref: SRV - 016- 005

Date: Sept. 02, 2016

Product: Honey Bee AirFLEX tables model year 2014, 15 and 16

Re: Bearing Replacement

Problem: Bearing failure, poor quality bearing will cause **FIRE**.

Solution: Remove and replace bearing on both right and left side of feeder deck drive roller with better quality bearing, equal to or better than bearing #UEL206-104D1W3.

Note: Replacement bearing must be a locking collar style bearing (as indicated by bearing part number).

