

Honey Bee Manufacturing Ltd. P.O. Box 120 Frontier, Sask. SON 0W0 Phone (306) 296-2297 Fax (306) 296-2165 email: <u>rick.norheim@honeybee.ca</u>

SERVICE BULLETIN

INFORMATION ONLY	FIX ON FAILURE	MANDATORY X

SVR 09-003


Date: Feb. 04, 2009

Product: 2009 WS Swather & Grain Belt Headers

Re: Improperly located bolt on <u>2009 WS & Grain Belt Headers</u> shipped from factory prior to Jan. 29, 2009

Problem: A bolt may have been incorrectly attached to either right or left deck, near the drive rolller end.

Solution: Check tables and remove bolt if found, **bolt must be removed to prevent draper damage.** <u>Figure 1</u>



Labor: .5 hr.

<u>**Reimbursement**</u>: Credit for Labor will be issued when a properly completedCF1 claim has been submitted to Honey Bee Mfg. Ltd.