

Honey Bee Manufacturing Ltd.

P.O. Box 120 Frontier, Sask. S0N 0W0 Phone (306) 296-2297 Fax (306) 296-2165

email: rick.norheim@honeybee.ca

SERVICE BULLETIN

MANDATORY

FIX ON FAILURE

INFORMATION ONLY

Ref: SRV - 011-003 Date: Apr. 30, 2011

Product: Ull Reels on all Honey Bee Product

Problem: In certain conditions it has been noted; that the pillow block bolt hole can tear or stretch

at end of reel bat.

Solution: Install bat bridge.

Ordering Information: Order Honey Bee part number as listed below.


Part no. Description Qty.

28005 Bat bridge 12 on 6 bat single piece reel

(Note: Required Quantities double for split reel)

Instructions:

- 1) Raise and lock reel in place using table reel locks.
- 2) Remove UII reel bat end shields.
- 3) Rotate reel remove end shields.
- 4) Loosen pillow block bolts if required.
- 5) Insert reel bat bridge (tap in as required).
- 6) Tighten pillow block bolts (12ftlb) and reinstall end shields.



Reimbursement: N/A

Labor: N/A