



SERVICE BULLETIN

MANDATORY**FIX ON FAILURE****INFORMATION ONLY** **Ref: SRV - 013- 002****Date: March 8, 2013****Product: Model Year 2012-- Grain Belt Header****Re:** Auger drum clearance.**Problem:** Drum contacting the carriage head bolt on the right hand side of adapter shell.**Solution:** Inspect for contact, if required replace carriage bolts and install kit assembly as per instruction below.**Ordering Information:** 1 - 94643 ADJ BOLT ASSY-AUGER ADAPTER**Labor Allowance:** N/A

REMOVE CARRIAGE HEAD
BOLTS AND SPACER.

**BEFORE****AFTER**

REPLACE SPACER &
BOLTS WITH
ASSEMBLY
SUPPLIED #94643.
Note: new
hardware does not
extend through
adapter shell.